


ATTACHMENT C






Ext Rear Stair Landing
Damaged / Repair/ replace



Ext Crawl Space Vent- Rear of Building
Wood rot/Stucco/Concrete/grading



Ext: Apt 1 Dining and Front Porch DH Windows



Ext 412 W Roosevelt St
Historic Plaque